
www.kondator.se

Axessline Ono 29

935-TB29
935-TB29W
935-TB29B

CONTENT:




x1



x2


1 MILL

Mill a hole in the table according to the correct dimensions. See !.




2 INSERT

Insert Axessline Ono into the milled hole. It must be inserted vertically into the hole.



! HOLE CUT-OUT DIMENSION




All measurements in millimeters.

!! FOR FLUSH-MOUNT


Check against each specific sample for each respective individual installation. Milling for flush-mount is at your own risk and responsibillity.

3 FIXATE SCREWS

Open the lid and use the two included screws to carefully fixate the product to the table.




Once the screw touches the edge, begin fastening the second screw until it touches the other edge. **Don't fasten it further than that.**



4 READY TO BE USED

Once all steps are completed, the product should be ready be used. Be sure to pair with the right accessories. Visit our website to find all possible accessories.



Kondator AB, Energivägen 8 - Box 121, SE-135 23 TYRESÖ, SWEDEN