Jser Manual 429-0P50



Cable Pipe, hanging

Stylish and practical cable tube. Can easily be shortened and extended up to 1252 mm. Each small duct adds about 56 mm to the length.

Part Check-List



x1








x2




x1

x1

1 Fix the top bracket 1 under the desk using the screws 2 and a screwdriver (not provided). Take not that the table thickness is recommended to be thicker than 20 mm.





- www.kondator.se

Assembly Guide

2 Begin to assemble the cable ducts③to the top bracket①. Examine the picture below to properly connect them together. Continue until all of them are assembled.

3 Using the same method, connect the assembly to the weighted bottom unit(4).

4 Organize and route the cables through the cable ducts (3) four channels. If needed, remove the cable duct assembly from top bracket (1) and bottom unit (4) to facilitate the process.

